

## 920-451 Other Nortel Certification

### Nortel ncde callpilot 2.x/3.0 unified messaging


**Practice Exam:** 920-451 Exams

**Exam Number/Code:** 920-451

**Exam Name:** ncde callpilot 2.x/3.0 unified messaging

**Questions and Answers:** 56 Q&As

( [Other Nortel Certification](#) )



Exam : [920-451](#)

"ncde callpilot 2.x/3.0 unified messaging", also known as 920-451 exam, is a Nortel certification. With the complete collection of questions and answers, TestInside has assembled to take you through 56 Q&As to your 920-451 Exam preparation. In the 920-451 exam resources, you will cover every field and category in Nortel Certification helping to ready you for your successful Nortel Certification.

Quality and Value for the 920-451 Exam TestInside Practice Exams for Nortel **Other Nortel Certification** Certification 920-451 are written to the highest standards of technical accuracy, using only certified subject matter experts and published authors for development.

#### **TestInside provide the professional Q&A.**

1. We offer free update service for three month.

After you purchase our product, we will offer free update in time for three month.

2. High quality and Value for the 920-451 Exam.

920-451 simulation test questions, including the examination question and the answer, complete by our senior IT lecturers and the Other Nortel Certification product experts, included the current newest 920-451 examination questions.

3. 100% Guarantee to Pass Your Other Nortel Certification exam and get your Other Nortel Certification Certification.

If you do not pass the Nortel Certification 920-451 exam (ncde callpilot 2.x/3.0 unified messaging) on your first attempt using our TestInside testing engine and pdf file, we will give you a FULL REFUND of your purchasing fee.

#### **use TestInside 920-451 Q&A ensure you pass the exam at your first try.**

TestInside professional provide Other Nortel Certification 920-451 the newest Q&A, completely covers 920-451 test original topic. With our complete Other Nortel Certification resources, you will minimize your Other Nortel Certification cost and be ready to pass your 920-451 tests on Your First Try, 100% Money Back Guarantee included!

[Nortel 920-451](#) Test belongs to one of the Other Nortel Certification certified test, if needs to obtain the Other Nortel Certification certificate, you also need to participate in other related test, the details you may visit the [Other Nortel Certification](#) certified topic, in there, you will see all related Other Nortel Certification certified subject of examination.

#### **TestInside Testing Engine Features**

Comprehensive questions and answers about 920-451 exam

920-451 exam questions accompanied by exhibits

Verified Answers Researched by Industry Experts and almost 100% correct

920-451 exam questions updated on regular basis

Same type as the certification exams, 920-451 exam preparation is in multiple-choice questions (MCQs).

Tested by multiple times before publishing

Try free 920-451 exam demo before you decide to buy it in Test-Inside.com.

Note: This pdf demo do not include the question's picture.

Exam : Nortel 920-451

Title : NCDE Callpilot 2.x/3.0 Unified Messaging

Version : Demo

1. A customer has installed two Communication Server (CS) 1000M RIs. 4.0 systems networked over the corporate WAN. Some of the system management functions of the CS 1000M can be performed by the Command Line Interface (CLI) as well as Element Manager. Which is a false statement regarding the use of Element Manager (EM) over the CLI?

- A. EM provides for drop down menus for prompt choices.
- B. EM provides full text descriptions of parameters and acronyms.
- C. EM allows the programmer to use the LD commands as well as using menus.
- D. EM increases speed and efficiency by organizing parameters to logical groups.

Answer: C

2. A customer has a network that contains several Communication Server (CS) 1000 RIs 4.0 systems. They are networked together via Virtual Trunks. The customer has limited bandwidth on the WAN links between sites and has an Optimized WAN link to carry Voice calls that use G.729A. Which configuration setup will ensure that G.729 is always used on a virtual trunk call between sites?

- A. No extra configuration is needed. Virtual Trunk calls always use G.729A CODEC.
- B. ? configure the virtual route to be in same zone as voice gateway channels and IP sets ? verify that the customer has G.729A as part of CODEC profile ? verify all zones at the site are configured with best quality for intrazone calls and best bandwidth for interzone calls
- C. ? virtual route is configured to be in different zone than the voice gateway channels and IP sets ? verify the customer has G.729A as part of CODEC profile ? ensure all zones at the site are configured with best quality for intrazone calls and best quality for interzone calls
- D. ? the virtual route is configured to be in a different zone than voice gateway channels and IP Sets for each system ? verify the customer has G.729A as part of CODEC profile ? ensure all zones at the site are configured with best quality for intrazone calls and best bandwidth for interzone calls

Answer: D

3. A company plans to have a Communication Server (CS) 1000 RIs. 4.0 Main Office (MO) site with one Media Gateway 1000B branch office (BO) site. The BO and MO will be connected via virtual trunks. Users at both sites will use Coordinated Dialing Plans (CDPs) to dial between the sites. They want long distance and CDP calls originating from the BO to route to the MO. All long distance calls will be tagged as international calls originating from the BO. They have no plans to expand the BO in the future. What is the most efficient way of routing calls from the BO?

- A. In the Gatekeeper, select the BO as the tandem endpoint for the MO.
- B. In the Gatekeeper, select the MO as the tandem endpoint for the MO.
- C. In the Gatekeeper, select the MO as the default route for CDP and international calls. All NPA ranges will need to be defined under the MO.
- D. In the Gatekeeper, all Numbering Plan Areas (NPAs), international numbers, and CDP steering codes should be defined under the MO.

Answer: C

4. A customer has a Communication Server (CS) 1000 RIs. 4.0 that they want to network with two other sites using the corporate WAN. Why must zones be configured with Element Manager before the Virtual Routes? (Choose two.)

- A. Zones determine NCOS privileges on a given trunk.
- B. Zones govern trunk groupings for TGAR assignment.
- C. Zones help determine Best Bandwidth CODEC per virtual trunk call.
- D. Zones manipulate CODEC selections and assigns bandwidth to a route.
- E. Zones provide call blocking based on Bandwidth defined for inter- and intra-zone calls.

Answer: CE

5. A company has two Communication Server (CS) 1000 RIs. 4.0 systems networked together with the following components: ? 800 IP Phone 2002 telephones at site A ? 600 IP Phone 2004 and 300 IP Phone 2002 telephones at site B Network Virtual Office is configured to enable IP telephone users to use their customized settings (i.e., autodials, key layout, etc.) on every IP telephone in the CS network. They want to use the Virtual Office Automatic Logout (VO\_ALO) feature to log out all IP telephone users from their IP telephones automatically. To configure the VO\_ALO feature, which task should you perform using the Command Line Interface (CLI)?

- A. Access Overlay LD 15, then enable VOLA.
- B. Access Overlay LD 15, then enable VO\_ALO.
- C. Access Overlay LD 11, then enable VO\_ALO for each Terminal Number (TN).
- D. Access Overlay LD 11, then enable Virtual Office Login Allowed (VOLA) for each TN.

Answer: B

6. A company has a two-site Communication Server (CS) 1000 RIs. 4.0 system (site A and B) providing IP-PBX services. Both systems are networked via a managed IP backbone. One system is a CS 1000 RIs. 3.0 Main Office (MO) and the other is a Media Gateway 1000 RIs. 4.0 branch office (BO). You configure the networked systems to enable the following: ? Users at the MO to call BO workstations by dialing 49xxx. ? Users at the BO to call MO workstations by dialing 2xxx. Which initial configuration task should you perform using Element Manager (EM)?

- A. Configure an LSC of 2 and a DSC of 49 in the MO.
- B. Configure a DSC of 2 in the MO and configure VNR in the BO.
- C. Configure a DSC of 49 in the MO and configure Vacant Number Routing (VNR) in the BO.
- D. Configure a Local Steering Code (LSC) of 49 and a Distant Steering Code (DSC) of 2 in the BO.

Answer: C

7. A company has a multi-site Communication Server (CS) 1000M-Chassis RIs. 4.0 system. If one of the Media Gateways goes into Survival Mode, they want Manual Control to restore the Media Gateway into Normal Mode. In Overlay LD 117, which command should you use to achieve this configuration?

- A. Chg Surv &lt;port> No
- B. Chg Surv &lt;port> Yes
- C. Chg Autosb &lt;port> No
- D. Chg Autosb &lt;port> yes
- E. Chg Swoto &lt;port> &lt;value>

Answer: C

8. A customer is installing a Communication Server (CS) 1000M-SG RIs. 4.0 at their Main Office (MO). They have a 10-member network using the corporate WAN and a Primary Gatekeeper. They want to use an Alternate Gatekeeper for redundancy. When are the Alternate Gatekeepers programmed? (Choose two.)

- A. during software installation and initial setup of the Signaling Server
- B. in Overlay LD 17 (Configuration) under the ADAN as an ELAN IP address
- C. in Overlay LD 117 (Configuration2) as an Embedded LAN (ELAN) IP address
- D. in Element Manager under the Signaling Server setting after the software has been installed

Answer: AD

9. A customer has just installed a Communication Server (CS) 1000M system. The CS 1000M is networked via the corporate WAN with several offices around the country. BARS is configured correctly for all telephones to use this route and the Virtual Trunks show IDLE. Traffic studies have shown that the majority of calls to remote locations are going out via the PSTN route instead of the virtual route. What in the configuration could cause this situation?

- A. CODEC is not assigned to the Virtual Trunk Route
- B. Bandwidth is incorrectly defined in the Zone Basic Property
- C. CODEC not defined for the zone in the Zone Basic Property
- D. Bandwidth is not defined for the Virtual Trunk Route and member trunks

Answer: B

10. A customer has installed a Communication Server (CS) 1000M RIs 4.0 system. Currently all 800 IP telephones at the site are registered to a single Signaling Server . This site has three installed media cards. What component(s) should be added at the site to ensure full redundancy for IP telephones?

- A. an additional Signaling Server must be installed and set as Failsafe
- B. an additional Signaling Server must be installed and programmed as Follower
- C. an additional Signaling Server must be installed and programmed as Alternate
- D. two additional media cards to ensure that all 800 IP telephones can register to media cards if the Leader Signaling Server fails

Answer: B

### [More 920-451 Information](#)

#### **Related 920-451 Exams**

[922-109](#) *Communications Server 1000 RIs.6.0 BARS/NARS*

[922-101](#) *Communication Server 1000 Linux Platform Architecture*

[922-111](#) *Communication Server 1000 to RIs.6.0 Upgrades for Technicia*

[922-081](#) *CallPilot RIs.5.0 Networking*

[920-457](#) *CallPilot RIs.4.0 Unified Messaging Exam*

[922-104](#) *Communication Server 1000 RIs.6.0 Upgrades for Engineers*

[922-071](#) *BCM50 RIs.3.0 & BCM200/400 RIs.4.0 Config & Maintenance*

[920-110](#) *NNCSS SL-100 Maintenance Certification Exam*

[922-098](#) *Communication Server 1000 RIs.5.0 Troubleshooting*

[920-805](#) *Nortel Data Networking Technology*

[920-806](#) *Nortel Advanced Data Networking Technology*

[920-220](#) *Nortel Converged Campus ERS Solution*

[920-502](#) *nncss-optera metro 3000*

[920-569](#) *nncds-optera metro solutions*

[920-246](#) *Nortel WLAN 2300 RIs.5.0 Implementation & Management*

[920-520](#) *Nortel Agile Communication Environment (ACE) RIs. 1.x Design & Engineering*

[922-094](#) *Communication Server 1000 RIs.5.0 Dialing Plan Design & IP*

[920-197](#) *BCM50 RIs.2.0 & BCM200/400 RIs.4.0 Config & Maintenance*

[922-099](#) *Communication Server 1000 RIs.5.0 Linux Platform Base & App*

[920-199](#) *BCM50 RIs. 2.0 & BCM200/400 RIs. 4.0 ICM*

#### **Other Nortel Exams**

[920-330](#)    [922-056](#)    [922-055](#)    [922-054](#)    [920-363](#)    [920-331](#)    [920-571](#)    [920-451](#)

[922-095](#)    [920-177](#)    [920-447](#)    [920-246](#)    [920-107](#)    [920-226](#)    [920-132](#)    [920-551](#)

[920-146](#)    [920-255](#)    [922-062](#)    [920-183](#)